



Firmware Note:
 Make sure TPSA33 is not enabled before AD5293 is powered up.