



Firmware Note:  
Make sure TPSA33 is not enabled before AD5293 is powered up.