

Firmware Note:
Make sure TPSA33 is not enabled before AD5293 is powered up.

Engineer: M. Bogdan	The University of Chicago
Drawn by: M. Bogdan	DAMIC Acquisition and Control Module
DATE: 7/25/22	Bias Generator 1
SPC#3019 ASM#3020	REV. A DRW. 3018 Sheet 17_4